



**GANDHI INSTITUTE OF ENGINEERING AND TECHNOLOGY UNIVERSITY,  
ODISHA, GUNUPUR  
(GIET UNIVERSITY)**

B. Tech (Fourth Semester - Regular) Examinations, April - 2025

**23BMEPC24004 - Quality Control and Reliability**

(Mechanical Engg.)

Time: 3 hrs

Maximum: 60 Marks

**Answer ALL questions**

(The figures in the right hand margin indicate marks)

**PART – A**

(2 x 5 = 10 Marks)

Q.1. Answer **ALL** questions

- |  | CO # | Blooms Level |
|--|------|--------------|
| a. Differentiate between Quality Assurance and Quality Control.  | CO1  | K1           |
| b. The following data represents the diameter of 10 parts: 10.2, 10.5, 10.8, 11.1, 10.9, 11.2, 10.6, 11.0, 10.7, 10.4. Calculate the mean and range. | CO1  | K2           |
| c. Explain the meaning and significance of AQL and LTPD.   | CO5  | K2           |
| d. A component has a constant failure rate of 0.005 per hour. Calculate the probability that the component will survive for 500 hours.               | CO6  | K3           |
| e. Briefly explain product life cycle with diagram.  | CO6  | K4           |

**PART – B**

(10 x 5 = 50 Marks)

Answer **ALL** the questions

2. a. Define Statistical Quality Control (SQC). How does SQC contribute to product consistency and customer satisfaction?

Marks: 5      CO # : CO1      Blooms Level: K1

- b. The XYZ Automobile Company produces engine shafts with a specified diameter of 50 mm. The quality control team collects 5 subgroup samples of 5 shafts each. Calculate the control limits for X bar chart and interpret the result.

Subgroup	Measurements
1	49.8, 50.2, 50.1, 49.9, 50.0
2	50.3, 49.7, 50.2, 50.1, 49.8
3	49.9, 50.0, 50.3, 50.2, 49.7
4	50.1, 50.2, 49.9, 50.0, 50.3
5	50.2, 49.8, 50.1, 50.3, 49.9

5      CO3      K5

(OR)

- c. The PQR Electronics company produces resistors with a specified resistance of 1000 ohms. The quality control team collects 5 subgroup samples of 5 resistors each. Calculate the control limits for X bar chart and R chart to interpret the result.

Subgroup	Measurements
1	980, 1020, 1000, 990, 1010
2	1010, 980, 1000, 1020, 990
3	990, 1010, 980, 1000, 1020
4	1000, 990, 1010, 980, 1020
5	1020, 1000, 990, 1010, 980

5      CO3      K5

- d. What are the various uses of control charts in a manufacturing environment? Explain how control charts help in process monitoring.

5      CO3      K4

- 3.a. Differentiate between single, double, and multiple sampling techniques with suitable examples.

5      CO2      K2

- b. A process engineer records the following number of surface defects per square meter of material processed:  
Construct the U-chart for result interpretation.

Sample	Area (m <sup>2</sup> )	Defects
1	5	1
2	4	3
3	6	2
4	5	1
5	5	6

5 CO3 K5

(OR)

- c. Draw and explain the Operating Characteristic (OC) curve for a single sampling plan.
- d. A quality control team monitors the number of defects in a sample of 10 units of a product. The data collected over 10 samples is: 8, 6, 7, 9, 5, 8, 6, 7, 10, 9 . Construct a C chart and determine whether the process is in control or not.
- 4.a. Compare the Kaizen approach with traditional improvement models. How do Quality Circles support the Kaizen philosophy?
- b. Describe the role of training and education in Total Quality Management, including the necessary skills and competencies for quality professionals.

5 CO5 K5

5 CO3 K5

5 CO4 K5

5 CO4 K5

(OR)

- c. Explain the philosophy and principles of JIT. How does JIT contribute to quality improvement and waste reduction?
- d. What are the key challenges and obstacles to implementing Total Quality Management, and how can organizations overcome them?
- 5.a. A system consists of 2 components in series, with the first component having a reliability of 0.95 and the second component being a parallel combination of 2 sub-components with reliabilities of 0.8 and 0.7. Calculate the overall system reliability.
- b. Explain the concept of hazard rate and its significance in reliability engineering.

5 CO4 K5

5 CO4 K5

5 CO5 K4

5 CO5 K4

(OR)

- c. A mechanical component has a Weibull shape parameter  $\beta = 1.5$  and scale parameter  $\eta = 1000$  hours. Determine the reliability at 500 hours and the mean time to failure.
- d. A system consists of 2 parallel branches, each containing 2 components in series. Branch 1 has components with reliabilities of 0.9 and 0.8, while Branch 2 has components with reliabilities of 0.85 and 0.95. Calculate the system reliability.
- 6.a. Describe the role of preventive maintenance and predictive maintenance techniques in reliability enhancement.
- b. Differentiate between unit redundancy and standby redundancy. Illustrate with practical examples where each type is effectively applied.

5 CO5 K4

5 CO5 K4

5 CO6 K4

5 CO6 K2

(OR)

- c. Explain the stages of product development with suitable diagram and example.
- d. Describe the various stages of the product design process. How do considerations of reliability and maintainability influence each stage?

5 CO5 K4

5 CO5 K4

--- End of Paper ---