Tota	al N	umber of Pages:	02			B PCME
210		Introduction I	n To Physical I BRANCH: AUT T M Q.	O, MANUTECH ime: 3 Hours ax Marks: 70 CODE: B1124	Engineering Ma , MECH, PE	aterials
		Answer Questic The fig			and any five fro n indicate mark	
Q1 <sup>10</sup>	a) b) c) d) e) f)		ion and () plane i veen substitutiona -strain diagram fo vector ? What is i veen eutectic and ostructure betwe	in a cubic unit cel al and interstitial s or brittle and duct its significance? I eutectoid reactio	solid solutions. ile materials.	<sup>210</sup> (2 x
210	g) h) i) j)	Write two types of What are nano m Differentiate betw What is sintering	naterials? <sup>210</sup> veen thermosettir	210 ng and thermopla	210 stic materials.	210
<b>Q2</b> 210		principal slip plar Calculate the nur	nes and slip direct mber of vacancies icies formation is	tions for FCC me s per cubic meter 0.98eV/atom. Fu	in gold at 900 <sup>0</sup> c. t urthermore, the de	he <b>(5)</b>
<b>Q3</b>	a) b)	resolved shear st A single crystal of that a tensile stu resolved shear s	tress? of a metal that ha ress is applied p tress for this ma	the FCC crystates the FCC crystates the FCC crystates the second strain of the second strain of the second strain se Strain second strain seco	ear stress. What al structure is orier 00] direction. If th a , calculate the m on the (111) plane	nted such <b>(5)</b> ne critical nagnitude
Q4	a) b) c)	AB system) and s Consider a Pb-70 (i) The amounts a (ii) The amounts	norphous phase of show salient poin 0% Sn alloy. Dete and compositions and compositions	diagram of any tw ts on it ermine s of each phase a s of each phase a	vo component sys t 184ºC, it 182ºC	(4)
210 Q5	a) b)	brief the different From the iron-iro	reactions that ta on carbide phas fractions at equil	ke place in this sy e diagram , for ibrium at the follo	a 0.2%C steel, r wing temperatures	name the (5)

Q6	a)	What is a T-T- T diagram? Why it is also called as isothermal transformation diagram? How is this transformation influenced by addition of chromium and nickel?	(5)			
210	b)	With respect to isothermal transformation diagram explain what transformations will take place when a steel with 0.5%C is cooled at a (i) slow rate and (ii) fast rate. How is this transformation influenced by addition of chromium and nickel?	(5)			
Q7	a)	Describe the Jominy end quench test. Draw the hardenability curves for plain carbon steel and different alloy steels. What is the significance of these curves.				
210	b)	Describe how steel is designated. What are alloy steels? Explain the composition, properties and applications of following stainless steels: I)austenitic and ii) martensitic.	(5)			
Q8	a)	1 71	(5)			
	b)	Explain their advantages over conventional transmission devises. What do you mean by naonmaterial?				



210 210 210 210 210 210 210 210 210 210