QP	C: RJ1800	O1163 AR - 18		Reg. No.							
	OF ENGINEERIN	GIET MAIN C	AMPUS	S AUTONON	MOUS GUI	NUP	UR	- 76	5022		
	1	B. Tech	n Degr	ee Examina	ations, Ju	ne –	202	21			
			(Sixth Sem	lester)						
0.00		BMEPE 6040 -	QUAL	ITY CON	FROL AN	ID F	REL	IAE	BILIT	Ϋ́	
Σ	ORIADA		(Mec	hanical En	gineering	5)					
Гime	: 2 hrs	Anov	TOP ATT	Questions			N	laxin	num:	50 M	lark
		Answ The figures in the ri		-	dicate mar	·kc					
PA	RT – A:	(Multiple Choice Questions)	Sittian	u mu gn m	urcate mar	11.5•	(1)	x 10 :	= 10 N	Aark	(s)
		ALL questions						٦	CO#]	ſ₽	O#]
<u>0.1.</u> a.			canabil	ity. If the pr	ocess mean	chif	te h	-	2011]	[I]	0"]
а.	A process maintains six-sigma process capability. If the process mean shifts by as much as 1.5 standard deviation from the centre, the proportion of										
		forming produced is									
	(i)	6 ppm	(ii)	3.4 ppm							
	(iii)	1350 ppm	(iv)	2700 ppm	1						
b.	Quality	trilogy that focusses on univ	versal v	vay of think	king of qu	ality	wa	s			
	proposed by										
	(i)	Joseph M. Juran	(ii)	Philip B.	Crosby						
	(iii)	W. Edwards Deming	(iv)	Kouru Isł	nikawa						
c.	The pro	ocess response converted into S/N	N ratio is	s always	·						
	(i)	Minimized	(ii)	Maximize	ed						
	(iii)	Set to zero	(iv)	Set to nor	n-zero value	e					
d.	Which	one of these is a dimension of qu	ality?								
	(i)	Hazard rate	(ii)	Process c	apability						
	(iii)	Control limits	(iv)	Performa	nce						
e.	Quality characteristics are classified into variables and										
	(i)	Attributes	(ii)	Standards							
	(iii)	Specifications	(iv)	Constants	5						
f.		tion nonconforming control cha				ry dı	ue to	0			
	(i)	 Sample size	(ii)	Number units in a	of nonco sample	onfor	min	g			
	(iii)	Binomial distribution of occurrence of number nonconforming units in a sample	(iv) Binom	Normal nial distributi	approximat on	tion	0	f			
g.	The consumer's risk means the probability that the consumer will										
	(i)	Accept a bad lot	(ii)	Accept a	good lot						
	(iii)	Reject a bad lot	(iv)	Accept a	bad lot						
h.	In double sampling plan, decision is made based on										
	(i)	First sample only	(ii)		s from the	first	t an	d			
	(iii)	A sample from the first lot and another sample from the last lot	(iv)	the comb	om the first bined nonco oth the sam	onfor					

	i.	It is des	irable to have C _p value				
		(i)	greater than or equal to one	(ii)	smaller than one		
		(iii)	greater than equal to two	(iv)	smaller than two		
	j.			the time	e to failure of products that have		
		a varyir	ng failure rate.				
		(i)	Binomial	(ii)	Exponential		
		(iii)	Weibull	(iv)	Poisson		
	PA	ART – B			(2 x 5	= 10 Mark	s)
<u>Q.2.</u>	Answe	er ALL qu	uestions			[CO#]	[PO#]
a.	Expla	in Qualit	y Function Deployment (QFD).			1	1
b.	What	do you n	nean by Average Total Inspection	(ATI)?		1	1
c.	What	do you n	nean by Juran's quality triology?			2	1
d.	What	is a conti	nuous sampling plan?			3	1
e.	Expla	in redund	lant and standby systems?			4	1

PART – C: (Long Answer Questions)

(6 x 5 = 30 Marks)

[CO#]

[PO#]

2

Marks

Answer ANY FIVE questions

3. Control charts for \bar{x} and R are maintained on a quality characteristic. The (6) 1 2 sample size is n = 6. After 30 samples, we obtain,

 $\sum_{i=1}^{30} \bar{x}_i = 6000$ and $\sum_{i=1}^{30} R_i = 150$

Find the three-sigma limits for the \overline{x} and R chart.

Assume that both charts exhibit control. If the specifications are 200±5, what are your conclusion regarding process capability?

- 4. A process is being controlled with a fraction nonconforming chart. The process (6) 1 average has been shown to be 0.07. Three-sigma control limits are used and the procedure calls for taking daily samples of 400 items. (a) Calculate the upper and lower control limits (b) if the process average shifts to 0.10, what is the probability that the shift would be detected on the first subsequent sample? (c) What is the probability that the shift would be detected on the first or second sample taken after the shift?
- 5. Samples of n=6 items are taken from a manufacturing process at regular (6) 2 2 intervals. A normally distributed quality characteristic is measured and \bar{x} and S values are calculated for each sample. After 50 subgroups have been analysed, we have

 $\sum_{i=1}^{50} \overline{x_i} = 1000$ and $\sum_{i=1}^{50} S_i = 75$

Compute the control limits for \bar{x} and S charts. If the specification limits are 19 ± 4 , what is your conclusion regarding the ability of the process?

6. The following data represent the number of nonconformities per 100 m² of (6) 2 2 fabric from a textile mill. Construct a c-chart for the number of nonconformities.

Sample Number	Number of Nonconformiti es	Sample Number	Number of Nonconformitie s
1	5	14	11
2	4	15	9
3	7	16	5
4	6	17	7
5	8	18	6
6	5	19	10
7	6	20	8
8	5	21	9
9	16	22	9
10	10	23	7
11	9	25	5
12	7	25	7
13	8		

7. Discuss Taguchi's philosophy for quality improvement. Discuss his loss (6) 3 1 function and its contribution.


2

2

3

(6)

8. Three components A, B and C are placed in parallel to make a subassembly in a circuit board. Determine the system reliability for 2000 h of operation and find the mean time to failure. Assume that all three components have an identical time-to-failure distribution that is exponential with a constant failure rate of 0.0005/h. What is the mean time to failure of each component? If it is desired for the system to have a mean to failure of 4000 h, what should the mean time to failure be for each component?



- 9. A sample of 12 electronic components is tested for 1000 h with no replacement (6) 4 of failed components. The time to failure is exponentially distributed. Three components failed within the prescribed test time, the failure times being 650, 680 and 720 h. Estimate the mean time to failure and the failure rate. Find a 90% confidence interval for the mean time to failure.
- 10. Distinguish between single level and multilevel sampling plans for continuous (6) 4 1 production.

--- End of Paper ---