Registration No. :											
--------------------	--	--	--	--	--	--	--	--	--	--	--

Total number of printed pages - 2

B. Tech

CPME 6401

Seventh Semester (Special) Examination – 2013 METROLOGY, QUALITY CONTROL AND RELIABILITY

BRANCH: MECH

QUESTION CODE: D 398

Full Marks - 70

Time: 3 Hours

Answer Question No. 1 which is compulsory and any five from the rest.

The figures in the right-hand margin indicate marks.

Answer the following questions :

2×10

- (a) Name the machines on which the major and minor diameters of screw threads are measured.
- (b) Differentiate hole basis and shaft basis system of fits.
- (c) What do you mean by calibration?
- (d) Define circularity.
- (e) What is meant by reliability?
- (f) Name the different elements of spur ge which requires spection.
- (g) Distinguish assignable and random cause of variation.
- (h) What is the heist limit of AQL?
- (i) Show the shape of an ideal sampling plan court
- (j) What does an acceptance sampling ensure?
- 2. Determine the tolerances on the hole and the shaft for a precision running fit designed by 50 H7/g6. Given that :

50mm lies between the range of 30-50mm.

 $i = 0.46(D)^{1/3} + 0.001(D)$ micron

Fundamental deviation for H hole = 0

Fundamental deviation for g shaft = $-2.5D^{0.34}$

IT7=16i and IT6 = 10i

Determine the actual maximum and minimum sizes of the both hole and shaft and maximum and minimum clearances.

- Define line standard and classify it depending upon the importance of 3. standard. 5 (b) Differentiate accuracy and precision. Describe two different methods of testing flatness of a surface, stating 4. advantages and limitations of each. A lot contains 1000 items out of which 10 are defective is to be inspected. A 5. sample of 36 items is taken and if it contains 0 defective, the lot is accepted. If it contains 1.2 or 3 defectives in first sample then a second sample of 59 items is taken and if total number of defectives in 1st and 2nd samples is less than 3 the lot is accepted. Calculate the probability of acceptance of the lot. 10 Describe various sampling techniques. 5 6. Explain AOQ and AOQL. 5 (b) Using Markov model briefly explain the availability of single repairable system. 7. 5 Explain and differentiate maintainability and vailability 5 (b) Write short notes on any four of the following: 2.5×4 8. TQM (a)
 - Quality circle (b)
 - (c) Geometric tolerance
 - Sequential sampling plan (d)
 - Accuracy (e)

CPME 6401 2 -C